20 November, 1969

MEMORANDUM TO: CHIEF,

STAT

STAT

FROM

: SAFE TECHNICIAN

SUBJECT

: CLASS V (HILLSIDE) CABINETS

Based on a recent examination of cabinets Stock number 7110-082-6112, manufactured by Hillside Products, Newark, New Jersey and furnished on Order #70-W21022-WC1F, the following deficiencies were noted on 3 out of 5 of these units delivered to

- 1. Welds on inside of case at juncture of right side panel and top panel; the fillets measurements vary in depth from 1/4" to 1/2". Of the total weld length of 26" the weld fill metal is well joined to the side panel along it's full length of the weld(26"), but the weld fill metal fails to adhere positively for 15" of it's juncture with the top panel.
- 2. Welds on the inside of the case at juncture of rear panel and top panel; Fillet is irregular and varies in depth as in #1 above. Of the total weld length of approximately 19%" the weld fill metal is well joined to the rear panel along it's full length of the weld (19%"), but the weld full metal fails to adhere positively for 8½" of it's juncture with the top panel.
- 3. Weld build up and slag deposits are in excess. Sll along the inside weld portions where the sides and/or the top are joined excessive weld build-up indicates a non-positive weld joint.
- 4. SUSPENSION TRACKS: The "U" shaped metal tracks welded into each side of the interior of the cabinet is of a light guage metal, inadequate to withstand the wear which is ultimately certain to result from field use.
- 5. SUSPENSIONS: The roller sheels of the suspensions are inadequately lubricated as received and are not possessed of sufficient strength to withstand the wear to be expected from field use.

GENERAL: HEIGHT--It was noted that the height of the 4 drawer Hillside unit is 46%". The construction used would require 57%" over-all height for a 5 drawer unit. The Federal Specifications so not permit this much height, therefore this Hillside Manufacturer cannot furnish 5 drawer cabinets should we require them. This also would mean having more than one make of cabinet (instead of standardizing), with the requirements for spare parts to be increased accordingly.

LABEL: It was noted that the protection label designated 20 man minutes against surreptitious entry protection. The Federal Specifications requires 30 man minutes against surreptitious entry.

MORI/CDF)



HARDPLATE: In front of combination lock consists of 2 pieses each ¼" thick. It appears extremely doubtful that this would furnish sufficient protection to withstand a 10 minute forced entry test.

QUALITY CONTROL: It was noted that in dis-assembling the lock the splane keys were able to be pulled out by hand, which would definitely throw the lock combination out of calibration after the lock was used a few times. Also the hardplates and the lock mounting plate (four screes which hold the lock rigid) just float freely inside the drawer head. The rigidity can only be accomplished then the drive cam is screwed onto the spindle and the spline key inserted and tightened, thus preventing the lock mounting plate from shifting. It is highly improbable that these plates will not shift furing shipment thus causing a bind and also where the threaded spindle goes through the plates, there will be a tendency for this spindle to bind on the free floating handplates. It was also noted that all four lock case screws were loose at least a % to ½ a turn and on some a full turn.

CONCLUSIONS: The under-signed does not believe that the cabinets manufactured by Hilldide (class V), could pass the test for Forced Entry prescribed in the Federal Specifications, either from the standpoint of hardplate protection around the combination lock or from a chisel and sledge attack along the welds where the top panel is fastened to the case. Neither could this suspension and tracks withstand the 50,000 cycle test as prescribed in Federal Specifications AAF-358-E and changes. There definitely appears to be sufficient doubt as to the ability of this Hillside Class V cabinet to pass the required tests and as far as the undersigned is concerned I personally recommend that they not be considered acceptable for our Agency use.

RECOMMENDATIONS:

		TEATER OF THE PARTY OF THE PART				
pendi				of the Hills	i de Class V c abin own agen cy.	ets be suspended
cabin		That appropon hand at	riate bests b	e conducted a	nd compiledion on	e or more of
•	3•	That all Hi	llside Class	V cabinets no	w in steck either	here at
	not be	issued for	overseas use	•	•	
		•			•	
•						
						STAŢ
•	•		•	•	TECHNICAL INSPEC	TOR

STAT

STAT